LAND ROVER

DEFENDER & COUNTY 110

FRONT	V8 PETROL ENGINES			3.9 ISUZU DIESEL ENGINES		
Estimated Lift: To 40mm	PART NUMBER	QTY	UNIT PRICE \$	PART NUMBER	QTY	UNIT PRICE \$
SPRING: TO 50 KGS: 30mm Lift	2761	1		2766	1	
NITROCHARGER SPORT	<u>1</u>	2		60037	2	
NITROCHARGER	N45F 1 5	Z		N45F 15	2	
SPRING: 51 TO 110 KGS	2751	1		2766	1	
NITROCHARGER SPORT	60037	2		60037	2	
STEERING DAMPER	OMESD32			OMESD32		
CASTER KIT	CALR1	1		CALR1	1	
CASTER KI	CALR2			UALNI		
COIL PACKER	OMELRCP1 4			OMELRCP1 4		

FRONT	2.5 DIESEL ENGINES			
Estimated Lift: To 40mm	PART NUMBER	QTY	UNIT PRICE \$	1
SPRING: TO 50 KGS: 30mm Lift	2751	1		
NITROCHARGER SPORT	60037	2		
NITROCHARGER	N45F 1 5	2		
SPRING: 51 TO 110 KGS	2767	1		
NITROCHARGER SPORT	60037	2		
STEERING DAMPER	OMESD32			
CASTER KIT	CALR1	1		
CASTER KIT	CALR2			
COIL PACKER	OMELRCP1 4			
REAR	ALL MODELS			

ALL MODELS

Estimated Lift: To 55mm	PART NUMBER	QTY	UNIT PRICE \$	2
SPRING: LIGHT LOAD: 25mm	2752]		
Lift	2152	1		
NITROCHARGER SPORT	60038			
NITROCHARGER SPORT	60146	2		3
HIGH ARTICULATION	60146			
SPRING: CONSTANT 300 KGS	2755	1		4
NITROCHARGER SPORT	60039			
NITROCHARGER SPORT	60147 6] 2		
HIGH ARTICULATION	00147			
SPRING: CONSTANT 500 KGS	2754 ₃] 1		
NITROCHARGER SPORT	60039			
NITROCHARGER SPORT	60147	2		5
HIGH ARTICULATION	00147			
COIL PACKER	OMELRCP3 4]		
REAR UPPER SHOCK MOUNT	FK64 6] 1		6

REMARKS:

Caution: Due to altered gearbox mounts on Models after 1998 any lift above OE ride height may cause front driveline vibration that can only be rectified by fitment of front double cardan joints.

Caster Kit will increase caster angle by 2°. Check manufacturer's specifications to determine if Caster Kit is required.

CALR1 suits 38mm wide control arms. CALR2 suits 44mm wide control arms.

2752 coil has a softer spring than OE coil. This is to provide improved ride quality with light loads only.

OE springs are designated as medium load springs.

Original inner helper coil, where fitted, must be re-installed with OME Coils.

8mm Steel Coil Seat Packer, refer to selection chart supplied with packer.

Important: To prevent possible over stressing of the spring, only one packer can be fitted under each coil seat.

When remaining stock of N45F is exhausted no further product will be available.

For high articulation vehicles it is recommended to replace rear upper shock mount with FK64 and matching shocks 60146 or 60147.

LAND ROVER

DEFENDER 130 MODEL

FRONT	2.5 DIESEL	2.5 DIESEL ENGINE		
Estimated Lift: 20mm	PART NUMBER	QTY	UNIT PRICE \$	
SPRING: TO 50 KGS	2751	1		
NITROCHARGER SPORT	60037	2		
NITROCHARGER	N45F 5	2		
SPRING: 51 TO 110 KGS	2767	1		
NITROCHARGER SPORT	60037	2		
STEERING DAMPER	OMESD32			
CASTER KIT	CALR1	1		
	CALR2			
COIL PACKER	OMELRCP1 3			

REAR **DIESEL ENGINE** Estimated Lift: To 40mm UNIT 2 PART NUMBER QTY **PRICE**\$ SPRING: LIGHT LOAD: 25mm 2 2755 1 Lift NITROCHARGER SPORT 60039 NITROCHARGER SPORT 2 6 3 60147 **HIGH ARTICULATION SPRING: CONSTANT 400 KGS** 2754 4 1 NITROCHARGER SPORT 60039 NITROCHARGER SPORT 2 60147 HIGH ARTICULATION COIL PACKER OMELRCP3 3 4 REAR UPPER SHOCK MOUNT FK64 6 1

REMARKS:

Caution: Due to altered gearbox mounts on Models after 1998 any lift above OE ride height may cause front driveline vibration that can only be rectified by fitment of front double cardan joints.

Caster Kit will increase caster angle by 2°. Check manufacturer's specifications to determine if Caster Kit is required.

CALR1 suits 38mm wide control arms. CALR2 suits 44mm wide control arms.

Important: 2755 has reduced spring rate from OE to provide improved ride quality for light loads. Original inner helper coil, where fitted, <u>must</u> be reinstalled with OME coils.

8mm Steel Coil Seat Packer, refer to selection chart supplied with packer. Important: To prevent possible overstressing of the spring, only one packer can be fitted under each coil seat.

Original inner helper coil, where fitted, must be re-installed with OME coils.

When remaining stock of N45F is exhausted no further product will be available.

5

6 For high articulation vehicles it is recommended to replace rear upper shock mount with FK64 and matching shocks 60147.